

## PHOTOGRAPHIC PLATES



Plate 1: Front elevation.



Plate 2: Steel frame.



Plate 3: Internal facing main doors.



Plate 4: Container at rear.



Plate 5: Right-hand elevation.



Plate 6: Sections of downpipe missing.



Plate 7: Minor cosmetic impact damage near front corner.



Plate 8: Previous repairs have maintained the barn in good condition.



Plate 9: Floor.



Plate 10: Central structure provides ducting to ventilate storage area.



Plate 11: Wear and tear to the main front doors.



Plate 12: View of barn from gate.