Energy performance certificate (EPC)			
39 Charlton Road TETBURY	Energy rating	Valid until:	8 September 2034
GL8 8DX		Certificate number:	4100-1015-0922-5421-3843
Property type	Detached house		
Total floor area	1	83 square metres	

### Rules on letting this property

Properties can be let if they have an energy rating from A to E.

You can read <u>guidance for landlords on the regulations and exemptions</u> (<u>https://www.gov.uk/guidance/domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance</u>).

### **Energy rating and score**

This property's energy rating is D. It has the potential to be C.

See how to improve this property's energy efficiency.

Score	Energy rating	Current	Potential
92+	Α		
81-91	B		
69-80	С		79 C
55-68	D	59 D	
39-54	E		
21-38	F		
1-20	G		

The graph shows this property's current and potential energy rating.

Properties get a rating from A (best) to G (worst) and a score. The better the rating and score, the lower your energy bills are likely to be.

For properties in England and Wales:

the average energy rating is D the average energy score is 60

## Breakdown of property's energy performance

### Features in this property

Features get a rating from very good to very poor, based on how energy efficient they are. Ratings are not based on how well features work or their condition.

Assumed ratings are based on the property's age and type. They are used for features the assessor could not inspect.

Feature	Description	Rating
Wall	Sandstone or limestone, as built, no insulation (assumed)	Very poor
Wall	Cavity wall, as built, insulated (assumed)	Good
Roof	Pitched, no insulation (assumed)	Very poor
Roof	Roof room(s), no insulation (assumed)	Very poor
Roof	Roof room(s), insulated (assumed)	Good
Window	Partial double glazing	Poor
Main heating	Boiler and radiators, mains gas	Good
Main heating control	Programmer, room thermostat and TRVs	Good
Hot water	From main system	Good
Lighting	Low energy lighting in 39% of fixed outlets	Average
Floor	Solid, no insulation (assumed)	N/A
Floor	To unheated space, no insulation (assumed)	N/A
Floor	Solid, insulated (assumed)	N/A
Secondary heating	Room heaters, wood logs	N/A

#### Low and zero carbon energy sources

Low and zero carbon energy sources release very little or no CO2. Installing these sources may help reduce energy bills as well as cutting carbon emissions. The following low or zero carbon energy sources are installed in this property:

• Biomass secondary heating

#### Primary energy use

The primary energy use for this property per year is 262 kilowatt hours per square metre (kWh/m2).

#### **Additional information**

Additional information about this property:

- · Stone walls present, not insulated
- Dwelling has access issues for cavity wall insulation
- Dwelling may be exposed to wind-driven rain

## How this affects your energy bills

An average household would need to spend **£3,330 per year on heating, hot water and lighting** in this property. These costs usually make up the majority of your energy bills.

You could **save £1,231 per year** if you complete the suggested steps for improving this property's energy rating.

This is **based on average costs in 2024** when this EPC was created. People living at the property may use different amounts of energy for heating, hot water and lighting.

#### Heating this property

Estimated energy needed in this property is:

- 28,976 kWh per year for heating
- 2,995 kWh per year for hot water

Impact on the envi	ronment	This property produces	7.7 tonnes of CO2
This property's environme D. It has the potential to be	1 0	This property's potential production	3.8 tonnes of CO2
Properties get a rating from (worst) on how much carb they produce each year.	· · ·		
Carbon emissions		These ratings are based or about average occupancy	and energy use.
An average household produces	6 tonnes of CO2	People living at the prope amounts of energy.	rty may use different

# Steps you could take to save energy

Step	Typical installation cost	Typical yearly saving
1. Room-in-roof insulation	£1,500 - £2,700	£606
2. Internal or external wall insulation	£4,000 - £14,000	£348
3. Low energy lighting	£95	£86
4. Solar water heating	£4,000 - £6,000	£91
5. Replace single glazed windows with low-E double glazed windows	£3,300 - £6,500	£99

Step	Typical installation cost	Typical yearly saving
6. Solar photovoltaic panels	£3,500 - £5,500	£529

#### Help paying for energy improvements

You might be able to get a grant from the <u>Boiler Upgrade Scheme (https://www.gov.uk/apply-boiler-upgrade-scheme)</u>. This will help you buy a more efficient, low carbon heating system for this property.

#### More ways to save energy

Find ways to save energy in your home by visiting www.gov.uk/improve-energy-efficiency

### Who to contact about this certificate

#### Contacting the assessor

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

Assessor's name	Toby Owen
Telephone	07950 022507
Email	tobymsowen@hotmail.co.uk

#### Contacting the accreditation scheme

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation scheme	Elmhurst Energy Systems Ltd
Assessor's ID	EES/015402
Telephone	01455 883 250
Email	enquiries@elmhurstenergy.co.uk

#### About this assessment

No related party	
29 August 2024	
9 September 2024	
RdSAP	
	29 August 2024 9 September 2024